



Installation of Hyperlite LCD-VNS (non swivel) Mount




Remove hanger hooks from cross bar and slide the assembly into the extrusion from top or bottom, tighten into place using wingnuts

Apply hanger hooks to rear of screen using top 2 holes only




Insert appropriately sized screw through hanger hook hole into the back of the monitor

Plan View showing how the bracket slides into the extrusion



Mount the screen on the hanger assembly using the hooks and tighten the thumb screws to secure it in place



DESIGN :

DATE:

REFERENCE:

© Trussworks 2010

The designs shown herein are the proprietary property of Trussworks and protected by copyright and other laws. This document is to be maintained in confidence. No portion of the information or design shown herein may be reproduced, electronically or otherwise, nor may any display be made from this design without written consent from Trussworks.

DRAWN BY: C.J.Morita